



2000 Falcon 900EX
SN 54 – PH-LAU



SCM ASSOCIATES, INC. 163 Main St. Penn Yan, NY 14527
Telephone: 315-536-2394 · sales@scmassociates.com · Website: www.scmassociates.com
Aircraft specifications, times and condition subject to buyer verification on inspection, Aircraft availability subject to prior sale.



2000 Falcon 900EX SN 54 – PH-LAU



SCM ASSOCIATES, INC. 163 Main St. Penn Yan, NY 14527
Telephone: 315-536-2394 • sales@scmassociates.com • Website: www.scmassociates.com

Aircraft specifications, times and condition subject to buyer verification on inspection, Aircraft availability subject to prior sale.



2000 Falcon 900EX
SN 54 – PH-LAU



SCM ASSOCIATES, INC. 163 Main St. Penn Yan, NY 14527
Telephone: 315-536-2394 • sales@scmassociates.com • Website: www.scmassociates.com

Aircraft specifications, times and condition subject to buyer verification on inspection, Aircraft availability subject to prior sale.



2000 Falcon 900EX
SN 54 – PH-LAU



SCM ASSOCIATES, INC. 163 Main St. Penn Yan, NY 14527
Telephone: 315-536-2394 · sales@scmassociates.com · Website: www.scmassociates.com
Aircraft specifications, times and condition subject to buyer verification on inspection, Aircraft availability subject to prior sale.



2000 Falcon 900EX SN 54 – PH-LAU

Aircraft Identification

Model: FALCON 900EX
Year of Manufacture: 2000, Delivery: 2000
Serial #: 900EX-54
Registration #: PH-LAU
Purchase Date: 3/7/2014

Usage (Times as of 1/23/2014)

Airframe Total Time(AFTT): 5,926
Landings/Cycles: 2,940

Interior Details (Updated: 05/2012)

Number of Passengers: 14

Seating: Newly reupholstered light beige perforated leather seats installed 05/12, four forward club seats, 4-place mid-cabin dining group, dual 3-place electrically operated light taupe berthable divans. **Sidewalls:** New sidewall covering installed 05/12. **Carpet:** New light taupe carpeting installed 05/12. **Refreshment Equipment:** Galley w/Turmix C420 automatic Nespresso machine, convection oven & microwave ovens. **Cabinetry:** New veneer varnish rework 05/12, Bird's-eye maple wood, mid-cabin electrically operated sliding table. **Entertainment Equipment:** Entertainment system w/12-disc CD changer/player, DVD multi-standard player, dual 17-inch LCD monitors, four 10.7-inch relocatable monitors, Airshow 400. **Accessories:** Light beige window panels. Lavatory: Forward crew & aft.

Exterior Details (Updated: 2014)

Colors: White, bronze lower w/black stripe.

Key Features

- ✓ Engine Maintenance Program
- ✓ CAMP (Computerized Maint. Prog.)
- ✓ 14 Passenger Interior
- ✓ Third Flight Management System
- ✓ Third Inertial Reference System
- ✓ Forward Crew Lav
- ✓ Traffic Collision Avoidance System (TCAS)
- ✓ SATCOM
- ✓ Engines and APU enrolled 100% JSSI
- ✓ Flight Data Recorder
- ✓ Thrust Reversers
- ✓ Auxiliary Power Unit
- ✓ Terrain Awareness and Warning System
- ✓ RVSM
- ✓ Cockpit Voice Recorder
- ✓ New Paint 2014 w/ Full Corrosion Check

SCM ASSOCIATES, INC. 163 Main St. Penn Yan, NY 14527

Telephone: 315-536-2394 • sales@scmassociates.com • Website: www.scmassociates.com

Aircraft specifications, times and condition subject to buyer verification on inspection, Aircraft availability subject to prior sale.



2000 Falcon 900EX SN 54 – PH-LAU

Engine Information

Engine Model: TFE731-60-1C , On Condition TBO: No

Engine Maintenance Program: Jet Support Services, Inc. - JSSI

	Serial No.	Total Time Since New	Time Between Overhaul	Cycles Since New
Eng 1 (L)	P-112276	5,810	6,000	2,870
Eng 2 (R)	P-112274	5,552	6,000	2,772
Eng 3 (L)	P-112275	5,537	6,000	2,770

Auxiliary Power Unit (APU)

Model : Honeywell GTCP 36-150 (F)

Total Time (Hours) Since New : 3,684

Maintenance Details

Maintained : EU OPS

Inspection: RVSM certified. EU Ops compliant. Aircraft entered into service 03/00. C-Check c/w 05/12. Landing gear overhauled c/w 04/12. Engines overhauled in 04/12. Dry Bay mod c/w 04/12..

Airframe Maintenance Program : Unknown

Airframe Maintenance Tracking Program : CAMP (Computerized Aircraft Maintenance Program)

Certification : RVSM

Equipment Details

General: Oxygen bottle, auxiliary 220V, 50Hz (1200-volt) power, Honeywell Primus 2000 auto throttle system. Lights: Tail recognition.

Addl Cockpit Equipment Details

General: AlliedSignal Mark V EGPWS, Honeywell MCS-6000 SATCOM w/triple handsets & one fax, heads-up display, Socata 96 3-frequency ELT.

Avionics

ADF : Dual Collins ADF-462. *AFIS :* Honeywell AFIS. *Autopilot :* Dual Honeywell Primus 2000 IFCS. *Avionics Package :* Dual Honeywell Primus 2000 IFCS / Pro Line 4. *Communication Radios :* Dual Collins VHF-422C. *CVR :* AlliedSignal 980-6022 CVR (120-minute). *DME :* Dual Collins DME-442. *EFIS :* Honeywell 5-tube. *FDR :* AlliedSignal 980-4700-025 DFDR (32 parameters-25-hours). *Flight Director :* Dual Honeywell Primus 2000 IFCS. *FMS :* Triple Honeywell FMZ-2000 w/5.2A software w/TOLD & dual *GPS.* Hi Frequency : Dual Collins HF-9034 w/Avtech SELCAL. *IRS :* Triple Honeywell LASEREF III. *Navigation Radios :* Dual Collins VIR-432. *Radar Altimeter :* Dual Honeywell RT-300. *SATCOM :* Honeywell MCS-6000 w/triple handsets & one fax. *TAWS :* AlliedSignal Mark V EGPWS. *TCAS :* Collins TTR-920 TCAS-II w/change 7.1. *Transponder :* Dual Collins TDR-94D Mode S w/Flight ID. *Weather Radar :* Dual Honeywell Primus 880 color.

SCM ASSOCIATES, INC. 163 Main St. Penn Yan, NY 14527

Telephone: 315-536-2394 · sales@scmassociates.com · Website: www.scmassociates.com

Aircraft specifications, times and condition subject to buyer verification on inspection, Aircraft availability subject to prior sale.